

## 2.6 Power Drawbar - Actuation and Tool Release

(Refer to Figure 2-6)

If the quill is fully retracted and the spindle in its oriented position, then the Power Drawbar can be actuated. There are three steps in this sequence:

1. The locking collar (ground plane) is placed around a recess at the top of the spindle and a switch detects this condition. Quill must be UP.
2. Air pressure is applied to a large area diaphragm which floats on springs relative to the machine frame. As soon as all lost motion is taken up, the internal force generated by the diaphragm deflects a hollow push rod to compress a stack of Bellville washers.
3. When the primary diaphragm has travelled full stroke, a secondary small area diaphragm strokes the inner rod of the dual drawbar downward to spread the collet surrounding the projection on the tool holder and rap the tool holder a light blow to release the tool holder from the spindle taper. Full stroke on the latter operation permits the tool change arm to proceed with its withdrawl cycle of the holder from the spindle.

For tool retention, the sequence of events takes place in the reverse of the Tool Release order. The open collet is closed by venting the secondary air chamber, and it is kept closed by further stroke of the inner drawbar which brings a locking ring around this collet. The collet has internal claws which are placed under a recess in the tool holder projection so that when the air in the primary chamber is released, the full spring force of 2100 lbs. is applied to these claws which keep the tool holder drawn up into the #35 taper of the spindle.

## 2.7 Tool Changer Arm

An air hydraulic cylinder drives a crank whose connecting rod is a rack. This rack rotates a pinion driving a large sprocket wheel engaging a chain. Attached to the chain and properly guided is the tool change arm. Extension and retraction of the piston rod will advance and withdraw the hand on its guiding member. A cam track provides the means to step the tool holder down in the tool change sequence to lower, then raise, the holder up into the spindle for engagement with the power drawbar.

The tool changer hand has two fingers which reach half way



around the tool holder. At the tip of each finger is a claw which is cam operated to release the tool at the retracted end of the hand's stroke and at the extended end of the stroke just before the power drawbar actuates. The mechanical advantage of the spring loaded linkage gives a firm grip to tools weighing up to 10 lbs. in their transit from carrousel to spindle and vice versa. Refer to Figure 2-7.







Figure 2-7: Tool Changer Arm







TO INSERT NEW TOOL :








FIG. 2-7A







### 2.7.2 Hydraulic Fluids

There is a single fluid bowl located above the tandem cylinder for arm motion. The following hydraulic fluids are approved for use in the Series I BTC:

- Mobil Velocite 6
- Shell Tellus 10 or 15
- Exxon Spinestic 10 or 34
- Gulf - Gulfspin 35
- Arco Diamond or Dura S-60
- Texaco Spindura 10

### 2.8 Knee Drive

Figure 2-8: Knee Elevation



Oil is controlled by a knob on the top of the filter/lubricator. To set the air flow, turn the knob clockwise to OFF then back clockwise to ON approximately 1/2 turn (3/4 turn is full flow).

#### WARNING

Do not operate system with the air system lubricator valve OFF.

If the system air pressure gets too low a pressure operated spring compensated spool will shut off the chip blower to save air. If the pressure drops below approx. 55 PSIG, the entire system will shut down to prevent possible damage to the fingers or the spindle shaft. The red LIMIT light will come on.


### 2.10.2 Air System Lubricants

The air system should be lubricated with Texaco Capella 22 oil. See data on lube bowl.



and spindle

K10 ✓  
TODC CHANGED  
SWITCHES




7. 4. 11

K10+

Center

Endura

PRE ORIENT 11  
I IVEX COMPLETE 12 9  
M



B 255

60

59



# A35 MILD

XTC K11 PIN <sup>AIR</sup> SOLENOID DRIVERS  
 6 PRIM DIAPHRAGM  
 + AIR BLOST  
 7 Secondary diaphragm



XTC K10 PIN  
 \* 9 SW M INOX Complete  
 \* 5 SW J Tool Arm Yone  
 10 H INSERT Tool  
 4 K Tool Arm Out  
 3 G Release Tool

SPE BOARD SEC Power Enable?  
 YES Pg 4-59

K9 HEAD SW INPUT  
 K10 Cartridge SW Input  
 K11 Solenoid Control Cables  
 K12 Spindle drive Cable



## 4.11 XTC BOARD FIGURE 1930760, SHEET 2

The (XTC) Solenoid and Tool Changer system switch interface board is the primary interface between the switches and solenoids. It also contains the interface to the AC spindle drive.

## 4.11.1 Driver/Receivers

IC57, 58, 59 and 60 are bus driver/receivers similar to the ones on the ZDI board. They will not be explained again here.

## 4.11.2 Address Decoding Circuits

All addresses on the XTC board are in the 1712XX range. Address decoder IC62 continuously monitors bits BRD7 through BRD12H and BBS7. When address 1712XX appears pin 9 of the decoder goes high. During any bus transaction BSYNC is asserted. This raises pin 7 of the decoder high, latching it in its state at that moment. BSYNC also strobes IC61 which latches the six address bits BRD1 through BRD6 as AL1 through AL6.

The XTC contains registers which accept data from the bus and others that place data on the bus. IC33 decodes the address bits to enable the proper registers.

Switch information from the head and carrousel tool station encoder are received through K9 on the XTC board.

171200	K9-5	Gear Latched SWR	
171202	K9-4	Hi Gear SWP	
171204	K9-3	Lo Gear SWQ	
171206	K9-13	Orientation Cycle Complete SWS	
171210	K9-14	Orientation Machine Reset SWU	
171212	K9-15	Ground Plane Engaged SWC	
171214	K9-16	Primary Stroke Complete SWD	
171216	K9-17	Start of Sec. Stroke SWE	
171220	K9-18	Ground Plane Released SWF	
171222	K9-19	Tool Pos SWA	
171224	K9-10	Tool Pos SWB	
171226	K9-9	Tool Pos SWC	Carrousel encoder
171230	K9-8	Tool Pos SWD	
171232	K9-7	Tool Pos SWE	
171252	K10-8	Pre-Orient SWT	


The information from the remaining carrousel switches is received




through K10 addresses.

171240	K10-5	Tool Arm Home SWJ
171242	K10-4	Tool Arm Out SWK
171244	K10-3	Release Tool SWG
171246	K10-10	Insert Tool SWH
171250	K10-9	Carrousel Index Step Complete SWM

See typical switch input circuit below.



The registers which accept data from the bus are called write only registers. Write only registers IC48 and IC49 provide data to the output drivers circuits which enable the solenoids. The outputs to the solenoids are through K11. See typical output driver circuit below.



The output on K11-M goes to the SPE board (Solenoid Power Enable), see Figure 1930760, which sends 24 VDC to the pneumatic solenoids. When address 171260 is decoded data, through IC51, goes to the speed control DAC IC18, and operational amplifier




## 4.13.5 Dynamic Braking

The dynamic braking functions consist of a small printed circuit card mounted to the base panel on the spindle drive and two power resistors.

The resistors are switched on and off; as the rate of deceleration is increased, the resistors will be on for a short time and off for a longer time.

## 4.14 Gear Shifting

An intermediate shaft in the transmission is driven by the motor generating a 4.46 to 1 reduction in spindle speed. This occurs when the bull gear on the spindle axis engages with a pinion on the intermediate shaft. Declutching the direct drive to the spindle through a neutral position to pick up the 4.46:1 reduction gear is entirely automatic, thus spindle speeds are 120 to 1080 RPM in back gear and 1100 to 5000 RPM in direct drive. The neutral position can be selected for set-up purposes; it is a position in which the bull gear is neither engaged with the low speed pinion nor engaged with the direct drive clutch.



Gear Shifting Arrangement

Figure 4-28 Gear Shifting




GEAR SHIFTING

Figure 4-29: Gear Shifting Flow Chart






Figure 4-30: Gear Shifting Flow Chart Continued



## 4.15 TOOL CHANGING DISCUSSION

The tool changing operation is performed in two parts:

1. Old tool removal and carousel alignment
2. Loading of new tool

The detailed steps are as follows:

1. Old tool removal and carousel alignment

1. Receive tool change command
2. Stop and null spindle, send Z home
3. Compare desired tool number with current tool number by reading the cam activated tool station position switches
4. Enable ground plane
5. Orient spindle
6. Enable primary diaphragm
7. Move rack arm (removing tool)
8. Enable secondary diaphragm
9. Replace old tool in carousel
10. Remove drive from rack arm

2. New tool loading sequence

1. Rotate carousel to the new tool
2. Drive arm forward and select the newly positioned tool
3. Insert tool in spindle
4. De-energize secondary diaphragm
5. De-energize primary diaphragm and ground plane to spindle
6. De-energize orientation
7. Remove drive from rack arm








Fig 7-13 ENCODER SWITCHES





LATCH IN HIGH GEAR POSITION






Figure 7-15: LATCH IN NEUTRAL POSITION



ADJUSTMENTS




Figure 7-16: LATCH IN LOW GEAR POSITION




# TABLE OF CONTENTS

SECTION		PAGE
1.0	INTRODUCTION	1-1
1.1	Purpose and Scope	1-1
1.2	Organization	1-1
1.3	Levels of Maintenance	1-1
2.0	MACHINE DESCRIPTION	2-1
2.1	Axis Drives	2-1
2.2	Quill and Spindle	2-3
2.3	Spindle Drive	2-4
2.4	Orientation	2-5
2.5	Tool Rack Carousel	2-7
2.6	Power Drawbar	2-9
2.7	Tool Changer Arm	2-9
2.8	Knee Drive	2-13
2.9	Lubricating System	2-15
2.10	Pneumatic System	2-19
2.11	Miscellaneous Function Control	2-20
2.12	Index System	2-21
2.13	Coolant	2-23
2.14	Chip and Coolant Shield	2-27
2.15	Specifications	2-27
3.0	POWER DISTRIBUTION	3-1
3.1	115 VAC Single-Phase Power	3-2
3.2	+24 VDC Power	3-4
3.3	-24 VDC Power	3-4
3.4	100 VDC Power	3-4
3.5	Fans	3-4
4.0	Control	4-1
4.1	Physical Arrangement	4-1
4.2	Control Logic Overview	4-3
4.3	Simplified Processor Operation	4-4
4.4	Operator's Main Control Panel	4-18
4.5	Operator's Switch Panel	4-28
4.6	Special Operations Panel	4-30
4.7	ZDI Board	4-32
4.8	CPL Board	4-42
4.9	RRS Board	4-47
4.10	NTP Board	4-51
4.11	XTC Board	4-58
4.12	SCA Board	4-61
4.13	Spindle Drive	4-62
4.14	Gear Shifting	4-64



CARD LOCATIONS  
LEFT TO RIGHT;  
LSI-11/2 CARD  
RRS CARD  
ZDI CARD  
NTP CARD  
CPL CARD  
XTC CARD  
ELC CARD



LOGIC  
VOLTAGE  
REGULATOR  
ADJUSTMENT

TB  
CONTROL  
SIGNALS

TB  
POWER  
SIGNALS

Figure 8-1:

Control Equipment Enclosure with  
Component Identification




D

C


B

A






01933506



# SPINDLE DRIVE ENC. T.B.




WIRE NOS.  
2, 3, 39, 101, 204, 205, 226, 230 THRU 234, 244 THRU 252,  
265, 266, 288 THRU 291, 299.

DESIGNED:		DATE:		THIS DOCUMENT/DELIVERED INFORMATION IS PROPRIETARY TO BRIDGEPORT MACHINES AND IS MADE AVAILABLE TO YOU FOR THE USE AND MAINTENANCE OF OUR PRODUCTS. ANY USE, REPRODUCTION, OR DISSEMINATION OF THIS INFORMATION FOR ANY OTHER PURPOSE IS PROHIBITED WITHOUT WRITTEN PERMISSION.	
DRAWN:		DATE:		TITLE	
CHECKED:		DATE:		SYSTEMS WIRING DIAGRAM	
APPROVED:		DATE:		SERIES I-BTC LOW PROFILE	
PROJECT NO.		MODEL NO.		SIZE	
846		BTC		D	
CODE IDENT NO.		DWG NO.		REV.	
1933506		1933506		0	
SCALE		DO NOT SCALE DWS		SHEET 6 of 8	

MATERIAL:		DIMENSIONING	
FINISH:		UNLESS OTHERWISE SPECIFIED	
MARKING: PER A027089		ALL DIMENSIONS ARE IN MILLIMETERS	
TYPE: , CLASS: , POINT		TOLERANCES	
REMOVE BURRS AND SHARP EDGES.		MM	
INTERNAL CORNERS (R16) MAX.		(INCH)	
DWG NO.		THIRD ANGLE PROJECTION	
PARTS LIST		MM	
NEXT ASSEMBLY		X = ±	
		ANGLE	





REF LINE 33


WIRE N  
39, 111, 230  
259 THRU 2

▷ REED SWITCH, MAGNETICALLY ACTUATED

DWG NO.	PART
NEXT ASSEMB	



D1933506



CAROUSEL ENCODER TRUTH TABLE

TOOL	PS-A	PS-B	PS-C	PS-D	PS-E
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0

SWITCH DEPRESSED = 0.0VDC ON "O" TERMINAL  
SWITCH RELEASED = 7.5VDC ON "O" TERMINAL

NOTES

REED SWITCH, MAGNETICALLY ACTUATED

WIRE NOS.  
39, 111, 230, 235 THRU 243  
259 THRU 264, 385 THRU 387

DWG NO.	PARTS LIST	NEXT ASSEMBLY
MATERIAL:		
FINISH:		
MARKING: PER A027099		
TYPE: , CLASS: , POINT		
REMOVE BURRS AND SHARP EDGES.		
INTERNAL CORNERS (R15) MAX.		

DIMENSIONING	
UNLESS OTHERWISE SPECIFIED	
ALL DIMENSIONS ARE IN MILLIMETERS	
MM	(INCH)
THIRD ANGLE PROJECTION	
TOLERANCES	
MM	$X = \pm .1$
ANGLE	$X = \pm .5^\circ$


DESIGNED:	DATE:
DRAWN:	DATE:
CHECKED:	DATE:
APPROVED:	DATE:
PROJECT NO.	MODEL NO.
846	BTC

**Bridgeport TEXTRON**  
Bridgeport Machines Division of Textron Inc.  
CONTROLS MANUFACTURING PLANT  
200 Precision Road, Norham, Pa. 19044

TITLE  
SYSTEMS WIRING DIAGRAM  
SERIES I-BTC LOW PROFILE

SIZE	CODE IDENT NO.	DWG NO.
D		1933506
SCALE: DO NOT SCALE DWG		
SHEET 7 OF		







1 PNEUMATIC BRAKE ONE MACHINE ONLY  
REPLACE WITH INDEX OPTION.



D 1780622

3

2




MATERIAL:		DIMENSIONING		DESIGNED	
		UNLESS OTHERWISE SPECIFIED ALL DIMENSIONS ARE IN MILLIMETERS		DATE: 79-4-03	
FINISH:		TOLERANCES		DRAWN	
HARDENING: PER A027099		MM	MM	DATE: 79-4-04	
TYPE: , CLASS: , POINT		(INCH)	X = ±	CHECKED	
REMOVE BURRS AND SHARP EDGES.		THIRD ANGLE PROJECTION	ANGLE X = ± 5°	DATE: 79-4-04	
INTERNAL CORNERS (R16) MAX.				APPROVED:	
DWG NO. PARTS LIST				PROJECT NO.	
NEXT ASSEMBLY				MODEL NO.	
				846 I-BTC	


3

2



[illegible]







M-144

OPERATING MANUAL

FOR THE

SERIES I BTC

MACHINING CENTER

THIS MANUAL PROVIDES INFORMATION WHICH IS PROPRIETARY TO BRIDGEPORT MACHINES AND IS MADE AVAILABLE TO YOU FOR THE USE AND MAINTENANCE OF OUR PRODUCTS. ANY USE, REPRODUCTION, OR DISSEMINATION OF THIS INFORMATION FOR ANY OTHER PURPOSE IS PROHIBITED WITHOUT WRITTEN PERMISSION.

THIS MANUAL CARRIES ADDITIONAL SAFETY PRECAUTIONS AND WARNINGS. READ AND OBSERVE THE REQUIREMENTS OF THE PREFACE AND THE ENTIRE PROCEDURES CONTAINED IN THIS MANUAL.

September 1980

***Bridgeport*** **TEXTRON**

Bridgeport Machines Division of Textron Inc.



4.15	Tool Changing Discussion	4-69
4.16	Axis Drive System	4-70
4.17	ELC Card	4-74
5.0	BASE AND HEAD DISASSEMBLY AND REASSEMBLY	5-1
5.1	Head and Ram Section	5-1
5.2	Tool Changer Section	5-12
5.3	Table, Saddle, and Knee	5-29
6.0	PREVENTIVE MAINTENANCE AND TROUBLESHOOTING	6-1
6.1	Preventive Maintenance	6-1
6.2	Axis Drive System Maintenance	6-4
6.3	Troubleshooting	6-5
6.4	Preliminary Electrical Checks	6-5
6.5	Axis Drive Troubleshooting	6-8
6.6	Error Codes	6-10
6.7	Use of ODT	6-10
7.0	DETAILED TESTS AND ADJUSTMENTS	7-1
7.1	Test Tapes	7-1
7.2	Diagnostic Tapes	7-2
7.3	Regulated Power Supply	7-10
7.4	Gib Adjustments	7-12
7.5	DC Servo Drive	7-16
7.6	Backlash Compensation	7-18
7.7	Adjustment Procedure Spindle Speed	7-20
7.8	Orientation Set-up	7-21
7.9	Z Home and Quill Switches	7-24
7.10	Ground Plane	7-25
7.11	PDB Switches	7-26
7.12	Arm Switches	7-31
7.13	Carrousel Switch Troubleshooting	7-32
7.14	Bull Gear Latch & Switch Cams	7-36
7.15	X or Y Axis Decel/Limit Switch Setup	7-38
8.0	PARTS LISTS	8-1
8.1	Control Equipment Enclosure	8-1
8.2	Power Equipment Enclosure	8-3
8.3	Operator's Main Control Panel	8-6
8.4	Pneumatics	8-8
8.5	Card Complement	8-8
8.6	Recommended Spare Parts List	8-9
9.0	OPTIONS	9-1
9.1	Tape Reader	9-1
9.2	Voltage Conversion	9-8
9.3	Rotary Milling Table	9-8
9.4	#35 MMT Quick Change Kit	9-9



M-143

PROGRAMMING MANUAL

FOR THE

SERIES I-BTC

MILLING, DRILLING & BORING MACHINE

WITH

BOSS 7.1 SOFTWARE

This manual provides information which is proprietary to Bridgeport Machines and is made available to you for the use and maintenance of our products. Any use, reproduction, or dissemination of this information for any other purpose is prohibited without written permission.

This manual carries additional safety precautions and warnings. Read and observe the requirements of the preface and the entire procedures contained in this manual.

December 1980

**Bridgeport** **TEXTRON**  
Bridgeport Machines Division of Textron Inc.



M-147

INSTALLATION MANUAL

FOR THE

SERIES I BTC

MACHINING CENTER

THIS MANUAL PROVIDES INFORMATION WHICH IS PROPRIETARY TO BRIDGEPORT MACHINES AND IS MADE AVAILABLE TO YOU FOR THE USE AND MAINTENANCE OF OUR PRODUCTS. ANY USE, REPRODUCTION, OR DISSEMINATION OF THIS INFORMATION FOR ANY OTHER PURPOSE IS PROHIBITED WITHOUT WRITTEN PERMISSION.

THIS MANUAL CARRIES ADDITIONAL SAFETY PRECAUTIONS AND WARNINGS. READ AND OBSERVE THE REQUIREMENTS OF THE PREFACE AND THE ENTIRE PROCEDURES CONTAINED IN THIS MANUAL.

DECEMBER 1980

***Bridgeport***® **TEXTRON**  
Bridgeport Machines Division of Textron Inc.



5. The speed reference voltage adjustment (P1) is made as follows:

1. Set the spindle speed to 2000 RPM.
2. Using a hand held tachometer, adjust P1 until the spindle runs at 2000 RPM.

### 7.8 Orientation Set-up

1. With power off to the control and no air connected, preset the two orientation regulators to the off state (full counterclockwise).
2. Connect the main air supply to the control and verify a setting of 75 PSI at the line regulator.
3. Adjust the orientation reset regulator (port C15 on the head manifold) for 25 to 30 PSI (hose closest to the head on the shot pin cylinder).
4. Turn power on to the control. Place the system in the SETUP state. Manually turn the spindle until the key faces the column.






Figure 7-7:

5. Loosen the set screws securing the 3 reed switches and slide the switches as far back from the head as the track will allow.
6. Locate wire #236 and #230 in the Control Enclosure on the terminal tracks and place a VOM across #230 (plus) and #236 (minus). You will be measuring +24 VDC.
7. Locate switch U and read the meter to determine if the switch is closed.
  - 0.0V = closed
  - 24V = open
8. Move switch U in towards head until the switch closes. Move it approximately 1/8" further and secure it in this positive.
9. Verify that the machine is in low gear.
10. Connect a terminal to the local port, remove K7 from the RRS card and enter ODT by pressing the BREAK key.
11. Enter: 171206/  
 Result: 171206/100001  
 Enter: 0 (ZERO)  
 Result: Orientation solenoid should energize



12. Adjust the regulator for shot-pin out (C14 on the head manifold) for 20 PSI.
  1. The shot-pin should engage the scroll plate
13. Manually rotate the spindle clockwise for approximate 90 degrees. The shot-pin should extend further due to the scroll plate step-off. You can feel the step off with your hand on the spindle.
14. Rotate the spindle counterclockwise until it stops.
15. Locate wires #111 and #230 on the terminal track in the Control Enclosure and place a VOM across #230 (plus) and #111 (minus). You will be measuring +24 VDC.
16. Move switch T in towards the head until the switch closes; move it approximately 1/8" further and secure it in this position.
17. Manually rotate the spindle clockwise to the keylock position. The shot-pin should extend into the keylock slot. You will not be able to rotate the spindle if it is in keylock.
18. Locate wires #235 and #230 on the terminal block in the Control Enclosure and place a VOM across #230 (plus) and #235 (minus). You will be measuring +24 VDC.
19. Move switch S in towards the head until the switch closes; move it approximately 1/8" further and secure it in this position.
20. Enter: 171206/  
Result: 171206/000000  
Enter: 1 (one) then hit the RETURN key  
Result: Shot-pin should retract.
21. Manually attempt to rotate the spindle in both directions. The spindle should rotate smoothly with no interference from the shot-pin.
22. Exit from ODT by pressing "P". Reconnect K7 on the RRS card. Rotate the spindle CW 90 degrees.
23. Place system in the Power Enable state.
24. Enter: M19 E0B (in MDI Mode)  
Result: System should correctly orient  
Enter: G86F300S2000M3X0Z1.5 E0B  
Result: System should change gears and orient correctly  
Verify: Correct cycle operation per Manual M-165, Section 5.



## 2.4 Orientation

Spindle orientation is done mechanically as part of a tool change cycle or by special command and can take place in any quill position. Orientation command will force the machine to go to low gear and allow the spindle drive motor to rotate the spindle at low speed. When minimum speed is detected, an air valve shifts to drive the piston of an air cylinder full stroke. The piston rod carries a shot pin to engage in a slot in a scroll plate attached to the bull gear. Advance of the shot pin into the orientation slot also removes the spindle speed command from the spindle drive motor. Refer to Figure 2-4.





Figure 2-4: Orientation




## 2.5 Tool Rack Carousel

This is a 24 position circular rack driven by a bidirectional air motor. Refer to Figure 2-5. The motor drives a Geneva mechanism with a position detection system. The detection system includes an encoder which determines the absolute position of the carousel and aids in the search for a particular tool. The direction of rotation is automatically selected with the tool change cycle achieving random selection by the shortest path.

The carousel can also be indexed while in Manual Setup operation. A pushbutton is located at the back of the machine for manual indexing but dual interlocks are provided to prevent simultaneous automatic carousel action. Power enable is possible only when the tool shield is in position.

An empty slot must be presented to the tool change arm if there is a tool in the machine spindle. 3" diameter tools are easily accommodated; however, if 4" tools are used they must be placed between 2 tools of 2" diameter or empty slots.

There is a special air blast directed upon the taper of the old tool entering the carousel and on the taper of the new tool as it leaves the carousel for the spindle. This ensures a clean, positive, contact with the spindle taper.








Figure 2-5: Tool Arm Carrousel



**PETRZELKA BROS. INC.**

1673 CEDARDALE RD.

P.O. BOX 1334

MT. VERNON, WA 98273

(206) 424-8095

## SAFETY INFORMATION

To prevent serious injury, you should observe the following basic safety precautions when using any machine tool or equipment.

### SERIES I BTC

### MACHINING CENTER

### WITH

### (BOSS 7.2 Software)

### MAINTENANCE MANUAL

M-168

DECEMBER, 1981

1040520

REV 0 DEC 81